

B007-1 ERRATA SHEET

Preface

Paragrapgh three assumes a working knowledge of the Transputer Development System.

Page 10

When using an IBM/B004, the B007 graphics board interconnects via Link 1 (not Link 0)

Page 12

When using an IBM/B004 the connections are as follows:

B004 Link 1 to B007 Link 1
B004 Subsys Socket to B007 Up Socket

Component layout

The component layout depicted differs from the board in minor instances.

Test Software Changes-RevA and RevB Host

Due to the timer 'tick' rate being different on the RevB Transputer, the B007 test software needs to be changed in one of the tests. In the 'typed occam' fold of the B007 test disk there is a fold marked 'EXE graphics test monitor'. Inside this EXE there is a fold marked 'delay' which uses the occam '?AFTER construct'.

'?AFTER ' arguement should be changed from:-

tick ? AFTER(now + 4400000)

to

tick ? AFTER(now + 44000)

The EXE should be re-compiled using the occam 2 compiler.